



TROUBLESHOOTING GUIDE FOR COMMON ISSUES

NO SIGNAL → Check Cable (damaged?) → Check Process Hole (Clear?) → Need A Cleaning Tool?

SIGNAL IRREGULARITY → Moisture Around Sensor Body? → Re-Mount Sensor Above Process Contamination

PHYSICAL DAMAGES → Diaphragm → Exposed Tip/Visible Damage → Shims to Reset the Tip Higher Up Into Process hole (\$30 fixes this)

PHYSICAL DAMAGES → Diaphragm → Aggressive Process Materials → Review to Change Diaphragm Material

PHYSICAL DAMAGES → Temperature → Over 750Df/400Dc → Call/Email TechSupport to discuss options

PHYSICAL DAMAGES → Bent ridged stem → Can't be repaired/consider new sensor

www.NoNonSensors.com

techsupport@nononsensors.com